



---

# Safe Composite Repairs – Substantiation Linking Repair Test Data to Observed Fleet Performance

FAA Workshop for Composite Damage Tolerance and Maintenance  
Chicago, IL July 19-22, 2006

**John M. Welch**

Associate Technical Fellow – Composite Structures  
Propulsion Systems and Structures

July 20, 2006

[john.m.welch@spiritaero.com](mailto:john.m.welch@spiritaero.com)

J.M. Welch 7/20/2006

- **Spirit Nacelle Composites Safe Repair Substantiation**

- \* **Test Coupon Data – Substantiates Capacity**
- \* **Service Related Repair Experiences – Substantiates Performance**
  - Start Bleed Duct Repair Kit**
  - Large Trans-Sleeve Repair Kits**
  - Inner Wall Overheat Repair Efforts**
  - Large Inner Wall Compliance Repair Kits**
- \* **Summary and Closing**
  - Conclusions of Experiences Linked to Repair Substantiation**
  - Recommendation**



Preparation for Repair Efforts Required Substantive Data

Prepared Test Plan Based on Available Information

Outlined Large Matrix of Potential Coupons

Performed Testing and Documented Results

Data Showed Structural Response was Acceptable



Alternate Materials from Substrate Were Tested




Tension




Compression




Large Beam  
Bending



## Example - Tension



## Example - Tension





## Realization of Performing Repair Required Mobile Solutions

Hardware Size and Scale not able to be easily shipped.

Difficulty in Shipping for Domestic Carriers was amplified for Foreign Carriers.


Time for Repair had to be minimized to reduce risk.

Unable to rely on available spares – repair must succeed.

Equipment and Logistics, Materials and Processes, all had to become “mobile”.

## Thrust Reverser Inner Wall Damage from Start Bleed Duct

- Bleed Valve Failure Repair Kit.
  - All necessary components to perform repair
  - Accompanied by detail repair instructions
  - Maintenance center estimated 30-45 days for effort.
- Accomplished repair on 3 units - took 5, 4, and 3 days respectively.
- Provided 8110, carrier provided 8130.





# Thrust Reverser Inner Wall Damage from Bleed Duct



Consolidated Repair Patch being placed



Cured Repair Patch




## Thrust Reverser Inner Wall Damage from Bleed Duct



← Restored Perforations

Final Painted Repair






3 Units  
Repair Area = 7 sq ft  
Exceeding 8000 cycles, 50000 hours (oldest)  
First performed circa 1997  
Was thought to be largest we would ever see

## Large Area Trans-Sleeve Repair

- **Trans-Sleeve Repair Kit, for foreign carrier**
- **All necessary components to perform repair**
- **Accompanied by detail repair instructions**
- **Hardware had been out of commission for over 1 year.**
- **Accomplished repair on 1 unit – took 10 days.**
- **Provided 8110, carrier provided 8130.**



## Large Area Trans-Sleeve Repair



Through Penetration

Several Stages of Core Repair


Innovative "Cavity" Repair

Perforate Restored




## Large Area Trans-Sleeve Repair

- **Trans-Sleeve Repair Kit – completed prior to paint**



## Large Area Trans-Sleeve Repair



1 Unit

Repair Performed on site at Foreign Carrier

Repair Area = 25 sq ft

6000 cycles, 48000 hours


Performed circa 2001

“Certainly” this was largest we would ever see

## Large Area Trans-Sleeve Repair - Collaborative



Carrier Provided Dimensions-  
We provided Everything else  
Including mylars for Indexing



Core Replaced and  
Taper Sanding Complete




## Large Area Trans-Sleeve Repair



↑  
Core Replaced



↑  
Solid Side Replaced




→  
Perforate Restored



## Large Area Trans-Sleeve Repair

- **Trans-Sleeve Repair Kit – completed**
- **Provided 8100, carrier provided 8130**



1 Unit  
Repair Performed by Carrier  
Kit Provided on Contract  
Repair Area = 15 sq ft  
1500 cycles, 16000 hours  
Performed circa 2001

# Thrust Reverser Inner Wall Damage from Overheat Issues



Overheat Damage at Blanket Seam

- Provided 8100
- Carrier provided 8130



Taper Sand



Bonded Repair

# Thrust Reverser Inner Wall Damage from Overheat Issues



Taper Sand

## Overheat Damage at Blanket Seam

24 Units

Repairs Performed on-site with "Carriers" as Tech Assist

Repair Area = 1 to 5 sq ft

6000 cycles, 32000 hours (oldest)

Performed circa 2002,2003,2004

## Bonded Repair



## Large Inner Wall Repair for Compliance



Necessary Tooling to get T/R into Repair Position

## Large Inner Wall Repair for Compliance



Special "Tent" for Facility Request



Core Removed



## Large Inner Wall Repair for Compliance



↑  
Core Replaced



↑  
NDI, Prior to Core Replacement



→  
Doubler Replaced

## Large Inner Wall Repair for Compliance



Doublers Replaced



Final Taper Sanding



Fwd & Mid Kits Applied



## Large Inner Wall Repair for Compliance



Fwd & Mid Kit Cured



Aft Kit Applied



## Large Inner Wall Repair for Compliance



Compliance Repair Kit Complete




NDI Being Performed

## Large Inner Wall Repair for Compliance



NDI Standard on-site

## Large Inner Wall Repair for Compliance




Details and Inclusions  
Were validated using  
several types of NDT  
methods – TTU shown

### LAMINATE THICKNESS

**A – 6 Ply**  
**B – 6 Ply**  
**C – 6 Ply**  
**D – 14 Ply**

NDI Plan required standard  
Containing all details of the  
Panel, and potential voids

## Large Inner Wall Repair for Compliance




Details and Inclusions  
Were validated using  
several types of NDT  
methods – TTU shown

### CORE TYPES

- A – Dense Aluminum**
- B – Double-Slotted Aluminum**
- C – Single-Slotted Aluminum**
- D – Grade 16 “High Dense”**

## Large Inner Wall Repair for Compliance



72 Units to comply, 4 complete  
Repairs Performed on-site for "Carriers"  
Repair Area = 33 and 35 sq ft (LH & RH)  
Just returned to service  
Performed 6/9 thru 6/22, 2006

- Inner Wall Repair Kit – completed
- Provided 8100, 8130



## Conclusions – Substantiation Data supporting Repair Performance

- **The substantiated test data created to support repair efforts has served its intended purpose. All test coupons supporting repair configurations were complied.**
- **Performance of repair kits to date has been as expected – capable.**
- **Noted performance and fleet experiences from repair kits applied and flying, for a significant amount of time, indicate that testing supports application for repair efforts.**
- **Inclusive, Pre-consolidated (with pressure) repair patches perform the best in our experiences.**
- **Structural testing must be supplemented with a capable NDI plan.**
- **The environment available for processing in the field may need to be artificially supplemented, i.e. “tents”, de-humidifiers, extensive cleaning, etc. Solvents and fluids will be present, so to ensure the data supporting the repair is not hindered, these considerations must be addressed – preferably in the test matrix.**
- **Total heat transfer must be considered and planned for, so as to support the data and processes being sponsored . This means power requirements become fundamental to larger repairs.**

## Recommendation – Preparing for Large Scale Composite Repair

- **First, it has to be at least recognized, that all sizes and locations that might be damaged, will. Our experiences have shown that we underestimated the potential, and eventual, larger damage/repair sizes required to support a composite, commercial nacelle.**
- **The role of logistics is large –Mobility is key and response to a damage event that will leave an airplane out of service has to be practiced and swift. Electrical requirements to support necessary wattage for large scale repairs has to be provided.**
- **Environmental issues may have to be manipulated to guarantee a capable repair.**
- **There will be a need to repair with materials other than the OEM substrate.**
- **Recommend that bonded kits be pre-plyed, pre-oriented, and pre-consolidated prior to being shipped on-site so that the greatest ability to preserve strength is guaranteed. This drives a secondary requirement that suppliers, other than the OEM, would need to be “qualified” to lay-up, orient, Quality Assure, and consolidate potential repair kits. Designated Centers of Excellence, perhaps?**
- **Potential Repair “Centers of Excellence”(?) entities must have available test data from industry, or supply their own data to correlate to their repairs to guarantee large scale capability.**
- **“Qualifying” repair entities should be required to include successful “proof-of-concept” work prior to carrying out the actual, large scale, composite repair.**