



Service Experience With Early BCA Composite Applications

Dan Hoffman
hoffmandaniel1@comcast.net

Daniel J. Hoffman
Technical Consulting

4/5/2007

12:01

CACRC Workshop
May 9, 2007



Intro / Overview



■ BCA Experience with Advanced Composites in Service

- 707 Boron Epoxy Foreflap
- 737 CFRP Flight Spoilers
- 727 Elevators
- 737 Horizontal Stabilizers

■ Update on CMH-17 Activities

- Chapter 13 **Defects, Damage & Inspection**
- Chapter 14 **Supportability & Maintenance**



Boeing 707 Boron Epoxy Foreflap



- IRAD funded
- Used non-traditional laminates in a sandwich monocoque
- Only a few built / Only one placed in revenue service; flew on NWA for a short period
- Performed well
- Removed from service when NWA elected to sell the airframe



Western Airlines 737-200 CFRP Flight Spoiler



- IRAD Funded
- Very small step; only replaced aluminum skins
- Used non-traditional laminates
- Performed well in service for a few years; removed when airframe sold
- Springboard to bigger things




83



NASA 737 Flight Spoilers



- Approximately 160 units deployed to Aloha, Air New Zealand, Frontier, Lufthansa, Piedmont, and VASP. Several airlines also had ground racks with coupon specimens
- 3 Graphite epoxy systems and one graphite thermoplastic system
- All in-service units inspected annually by Boeing P.I. Three units removed from service each year and tested to destruction to demonstrate adequate strength and stiffness
- As of final tracking date, 6/30/1989, the fleet had 2,593,741 flight-hours and 3,499,941 landings
- High time unit had 42,007 hours
- Units with thermoplastic resin suffered from Skydrol® degradation; removed from service; promptly forgotten
- Remaining units with epoxy resin systems remained in service many years; some may be flying today





Background



ACEE Composites Program

- The comprehensive NASA **AirCRAFT Energy Efficiency** program was initiated by NASA in late 1975 with the main purpose of developing new technologies to reduce fuel consumption in commercial transport aircraft
- The **ACEE** Composites program focused on achieving fuel efficiency through the use of lighter materials in existing aircraft structural components
- The **ACEE** Composites program targeted six aircraft secondary and medium primary components: the upper aft rudder of the Douglas DC-10, the inboard ailerons of the Lockheed L-1011, the elevators of the Boeing 727, the vertical stabilizers for the Lockheed L-1011 and Douglas DC-10 and the horizontal stabilizer of the Boeing 737





727 CFRP Elevator



- **5 shipsets built and certified / 4 placed in revenue service / one held as spares**
- **Performed well with original carrier until fleet sold in 2001**
- **Certification basis for these parts largely remains in place today**
- **I think of these as the “forgotten” components. (Bigger is better syndrome)**





Background **ACEE** 737 Composite HS Program



- As part of the **ACEE** program, Boeing redesigned, manufactured, certified, & deployed five shipsets of 737-200 horizontal stabilizers using graphite-epoxy composites
- Boeing 737 Composite Stabilizer Program Objectives:
 - Achieve a 20% weight reduction with respect to the existing metal structure
 - Manufacture at least 40% (by weight) of the components from composite materials
 - Demonstrate cost competitiveness of the structure
 - Obtain FAA certification for the structure
 - Evaluate the structure in service





737 HS Fleet Status



- **Five Shipsets were manufactured and certified in August 1982**
- **None in service at this time**

Shipset / Production Line #	Entry into Service	Airline	Current Status
1 / 1003	2 May 1984	A	Parked (60000 hours, 45000 flights)
2 / 1012	21 March 1984	A	Parked (62000 hours, 47000 flights)
3 / 1025	11 May 1984	B	Damaged beyond repair 1990; partial teardown completed in 1991 (17300 hours, 19300 flights)
4 / 1036	17 July 1984	B & C	Stabilizers removed from service 2002 (approx. 39000 hours, 55000 flights); partial teardown of R/H unit at Boeing
5 / 1042	14 August 1984	B & D	Stabilizers removed from service 2002 (approx. 52000 hours, 48000 flights); teardown of L/H unit at Boeing; teardown of R/H unit at NIAR, Wichita State



737 Stabilizer Description




STRUCTURAL ARRANGEMENT

- Stiffened Skin Structural Box arrangement with I-section stiffener panels: the entire skin/ stiffener combination was co-cured
- Bolted Titanium spar lugs: this concept used two titanium plates bonded and bolted externally to a pre-cured graphite-epoxy lug
- Back to back “C” sections secondarily bonded to form spars
- Honeycomb ribs
- Loads fed through spar lugs

MATERIAL

- NARMCO T300/5208
(Almost all fabric)





“Teardown” Approach




- **Inspect**
 - **Field Level**
 - **Depot Level**
 - **Factory Level**
 - **Advanced Techniques**
- **Disassemble**
- **Physical and Mechanical Test**
 - **Tg, Microscopy, Tension, Compression, Rail Shear, 3-Stringer Compression Crippling**



Production NDI Results



- **NDI with thickness mapping scan revealed stiffener disbonds**
 - **Known disbonds confirmed, other anomalies identified**







NDI – Then vs. Now



- NDI has become more sensitive, standards more rigorous
- Today's materials and manufacturing processes can produce laminates with far less porosity levels



1980's Sensitivity



Today's Sensitivity


(scans show same structure but different sensitivity level)



Physical Test Results (T_g)



- T_g values consistent but lower than limited “Quasi-Control” obtained from secondarily bonded spar
- NIAR results similar to slightly lower
- T_g remains significantly above service temperature





Physical Test Results



(Microscopy)

- Upper skin stringer showing noodle region
- Good compaction / low porosity
- Some microcracking evident; microcracks concentrated in resin rich & resin starved areas






Physical Test Results (Microscopy)



- Upper skin/stringer region taken in area of high attenuation
- Up to 5+% porosity noted in Boeing teardown; similar results reported from NIAR teardown

Ramifications?






Mechanical Test Results (Tension)



- 70 specimens from upper and lower skins of two stabilizer articles
- No significant degradation
- Shipset 4 equivalent to shipset 5
- Specimen curvature had little effect






Mechanical Test Results (Compression)



- 70 specimens from upper and lower skins of two stabilizer articles
- High scatter but no significant degradation / residuals higher than baseline for all regions / Shipset 4 equivalent to Shipset 5
- Scatter believed related to level of porosity






Corrosion & Lightning Strike Evaluation



- No evidence of lightning induced fastener pitting even though the teardown article leading edge & tip showed evidence of having been struck



Lab Test specimen following simulated lightning strike



Mechanically induced fastener pit found on teardown article fastener – no evidence of lightning induced damage



Conclusions



- **The teardown articles held up well in service**
 - CFRP -- Fasteners -- Moldable Plastic Shim
- **Almost all residual strengths above developmental baselines (Postcure / physical aging?)**
- **Evidence of no creep**
- **The results also illustrate the dramatic improvements that have taken place in the last 25 years with CFRP materials and our ability to produce and inspect them**
 - Production level NDI quality is moving into in-service environment
 - Newer, non-ultrasonic techniques are demonstrating great potential
- **The results validated Boeing's design, analysis, certification, inspection, maintenance, and repair philosophies:**
 - Damage occurred in service, inspections found the damage, & all damage was repairable



Some Other Le\$\$ons Along the Way



- **Some thermoplastic resin systems are Skydrol[®] sensitive**
- **Kevlar[®] “wicks” moisture**
- **Damage to composite structure often more extensive than visible to the naked eye**
- **Even state of the art NDI will not necessarily find all defects**



CMH-17 Chapter 13 Outline

13.0 Defects, Damage & Inspection (NEW)

13.1 Defects and Damage

13.1.1 Defect Types

13.1.1.1 Porosity

13.1.1.2 Local Resin-Content Variations

13.1.1.3 Ply Misorientation

13.1.1.4 Ply Overlaps and Gaps

13.1.1.5 Fiber Distortion

13.1.1.6 Embedded Foreign Objects

13.1.1.7 Poor Bonds

13.1.1.8 Improper Curing

13.1.1.9 Warpage

13.1.1.10 Improper Fastener Installation



Chapter 13 Outline (cont)



13.1.2 Damage Types

13.1.2.1 Fiber Breakage

13.1.2.2 Matrix Imperfections

13.1.2.3 Delaminations and Debonds

13.1.2.4 Combined Damages

13.1.2.5 Flawed Fastener Holes

13.1.2.6 Nicks, Scratches and Gouges

13.1.2.7 Dents

13.1.2.8 Puncture

13.1.2.9 Erosion

13.1.2.10 Heat Damage

13.1.2.11 Lightning Strike Damage

13.1.2.12 Damage From Fluid Ingression into Sandwich Panels



Chapter 13 Outline (cont)

13.1.3 Defect and Damage Sources

13.1.3.1 Manufacturing

13.1.3.2 Service

13.2 Inspection Methods

13.2.1 Non-Destructive Inspection

13.2.1.1 Visual

13.2.1.2 Tap Testing / Lamb Wave

13.2.1.3 Ultrasonics

13.2.1.4 Radiography

13.2.1.5 Shearography

13.2.2.6 Themography

13.2.2.7 Moisture Meters

13.2.2.8 Bond Testers

13.2.2.9 Eddy Current



Chapter 13 Outline (conc)



13.2.2 Destructive Inspection

13.2.2.1 Cross-sectioning / Photomicrographs

13.2.2.2 Deply

13.2.2.2 (Level-of-Cure Techniques)

13.2.2.3 Other ???

■ Status

Chapter 13 Draft well under way; ready for local review

Outline sections in black font have been populated with material from:

-- FAA Technical Document by Ilcewicz & Chang

-- Sections 2.6, 3.4, 6.3, 12.4 & 14.3 of current CMH-17

-- Lessons from service experience & teardown projects

Chapter 14 rewrite just getting underway

Welcome any additional inputs for either chapter



Acknowledgements



Thanks to:

- **Dr. Larry Ilcewicz -- FAA**
- **Thomas Walker, PE -- NSE Composites**
- **Peter Smith -- Consultant**
- **Lamia Salah & Dr. John Tomblin -- NIAR at WSU**