

GE90 Fan Blade Service Experience and Repair

Phil Griggs
Michael H. Schneider

FAA/EASA/Industry Composite
Damage Tolerance and
Maintenance Workshop

Amsterdam, Netherlands

May 10, 2007



GE90 Composite Fan Blade

- GE90 fan blade is an all composite (carbon / toughened epoxy) design
- Extensive material design allowables program conducted
- Blade geometry driven primarily by aerodynamics (performance), aeromechanics (stability), impact (bird strike), low cycle fatigue (CF loads) and high cycle fatigue (vibratory response)
- Certification test requirements included ...
 - > Operability – surge and stall; blade vibration
 - > Induction system icing
 - > Bird ingestion – 2.5 lb., 5.5 lb. and 8 lb. birds
 - > Foreign object ingestion – hail, water, ice slab
 - > Blade containment
 - > 2x overload (141% speed)
 - > Lightning strike
- Many of the engineering and certification tests included environmental exposure and effects of defects (mfg. defects and simulated handling damage)

Fan Blade Service Experience⁽¹⁾

“Single” Bird Ingestion Event October 4, 1998



Event Summary:

- Thrust level ... takeoff
- Aircraft speed ... V1 (~150 kts)
- Bird species ... Gray Heron
 - Weight ... ~3 lbs+
- Engine condition ... serviceable

Fan Blade Comparison



GE90-115B

GENx

GENx ... 3rd generation

“Multiple” Bird Ingestion Event September 9, 2002



Event Summary:

- Aircraft ... on approach
- Airspeed ... ~200 knots
- Ingestion ... both engines
- Bird species ... Canadian Goose
 - Weight ... ~8 lbs
- Engine condition ... serviceable

Service Experience ... approximately **eleven** years

Operational Experience ... over **8.9 million** engine flight hours

> Only **Three** Fan Blades ... retired from GE90 fleet 1st **6.0 million** engine flight hours

Reported Bird Ingestion Events ... **120** Base GE90 and **15** GE90-115B

> Including ... a Gray Heron and multiple Canadian Geese

GE90 Composite Fan Blade ... has significant positive service experience to



Fan Blade Field Sampling Program

- **Return “partial sets” of fan blades ... for inspection**

- Objective ... assess condition as blade ages
- Partial set = seven fan blades (-94B)
- Three airlines participating for each model
- Recommended age ... at planned inspections:
 - * 1000 to 1500 CSN
 - * 2000 to 2500 CSN
 - * 3750 to 4250 CSN
 - * 6750 to 7250 CSN
 - * 9750 to 10,250 CSN

- **Inspection includes:**

- Full non-destructive test
- Dovetail wear and MLE guard erosion
- Moisture content assessment

- **Data shared with FAA periodically**

FAA considers this program a benchmark in industry practice for safety management with new technologies



(Suction Side)

Serial No. ... CFNA 0804

CSN 5581

TSN 11485


Fan Blade Erosion and Wear Assessment

• *Erosion Assessment*

- Leading edge guard ... small amount observed directly on nose - quantification showed small erosion depth
- Tip region ... no erosion
- Trailing edge region ... no erosion
- Airfoil ... pressure side
 - * Polyurethane surface ... Some erosion observed
 - * Surface adjacent to leading edge guard ... some paint peeling

• *Wear Assessment*

- Dovetail pressure faces ... no significant wear
- Platform wear strips ... Some local wear observed



Serial No. ... CFNA 0804
CSN 5581
TSN 11485

Additional Fan Blade Inspections and Tests

- GE is conducting destructive tests on a field returned blade or blades on an opportunistic basis
- Testing includes:
 - > Residual HCF capability
 - > Residual LCF capability
 - > Residual static strength capability
 - > Inspection for undetectable damage via cutups and photo-micrographs
 - > Evaluation of moisture absorption at specific blade locations
 - > Natural frequency and mode shape characteristics

All characteristics have been within expectations

Fan Blade ... Repair Summary



- **Source Substantiated Repairs**

- ① Leading Edge Guard ... replacement
- ② Tip Cap ... replacement
- ③ Trailing Edge Guard ... replacement
- ④ Platform Wear Strip ... replacement
- ⑤ Dovetail Wear Strip ... replacement
- ⑥ Polyurethane Erosion Coating ... replacement
- ⑦ AF32 Erosion Coating ... Replacement

- **All these repairs are source substantiated ... some required significant testing to validate capability**

- **Most use production tooling**

- **Repair Source**

- CFAN ... located in San Marcos, Texas
- All “Source Substantiated” Repairs ... in production



(San Marcos, Texas)

Fan Blade ... Additional Repairs



- **Approved Repairs**

- ① Metal Adhesive Flash ... repair
- ② Platform Wear Strip ... frayed or disbond repair
- ③ Dovetail Wear Strip ... frayed or disbond repair
- ④ Polyurethane Erosion Coating ... local replacement
- ⑤ AF32 Erosion Coating ... local replacement
- ⑥ Composite Shank ... local blend repair
- ⑦ Paint ... local “touch up”
- ⑧ Composite Airfoil ... trailing edge delamination repair
- ⑨ Leading edge guard ... blend repair
- ⑩ Composite airfoil tip ... sealing repair
- ⑪ Composite airfoil ... impact repair

- **More repairs are in development**

- **Repair Source**

- CFAN ... located in San Marcos, Texas
- All “Approved” Repairs ... in production



(San Marcos, Texas)



Summary

- GE90 fan blade exhibiting excellent performance in the field
- Service evaluation program in place
- Fan blade repairs in place for most types of damage experienced