




Field Experience – Lightning Strike Damage of ANA B767




June 4, 2009

Nobuyuki Nakayama

ANA



Contents :

- ✓ **Field Experience of Lightning Strike Damages occurred on ANA B767 Airplanes**
 - ✓ **Preventive Actions taken by ANA**
 - ✓ **Requested Considerations/Actions to Airplane Manufactures**
- 
- A photograph of an ANA Boeing 767-300ER aircraft in flight, viewed from a low angle, flying over a blue sky with light clouds. The aircraft is white with blue accents on the tail and fuselage.




ANA Overview

➤ Domestic Operation □
50 cities/130 Routes

➤ International Operation □
24 cities/36 Routes

Number of Airplanes: 214 Airplanes





Lightning Strike Data:

**Period- from 01/01/2005 to 12/31/2006
(2 years)**

Fleet- ANA's all 767 (56 airplanes)



Damage: Lightning Strike

**Resource: ANA's maintenance control
system (SAP)**


Results:

✓ **Total 333 Lightning damages reported**

Higher Energy than Summer Thunder



Lightning Prone Region



JAPAN SEA

PACIFIC OCEAN



Majority of Lightning Strike occurs in Winter Season in this region

- 3 Major Regions – Winter Thunder:**
- ☐ West Coast of Norway
 - ☐ Great Lakes
 - ☐ Japan Sea Coast




767 Lightning Strike Experience

NO	ARTICLE	DATE	DEPARTURE	DESTINATION	PHASE	REMARKS
1	B-111111	11/11/11	CTS	KMQ	APP	







767 Lightning Strike Experience



Melted Rivet




Melted Rivet





767 Lightning Strike Experience

NO	ARTICLE	DATE	DEPARTURE	DESTINATION	PHASE	REMARKS
1	B000000	000000	NGS	HND	ARC	







767 Lightning Strike Experience



Shown with Tip End Panel removed.



Fastener Hole damaged.





RH H-STAB TIP



767 Lightning Strike Experience



ICN	ART OF	DATE	DEPARTURE	DESTINATION	PHASE	REMARKS
□	B□□□□□	□□□□□□□□	JM	KIX	JRO	




767 Lightning Strike Experience




H-Stab Tip Composite burned.



Window Sill melted.








747-400 Lightning Strike Experience



Rivets burned.




Nose Cowl Composite Skin burned. [|||||]



NO.4 ENG NOSE COWL SKIN

A320 Lightning Strike Experience

NO	ARTICLE	DATE	DEPARTURE	DESTINATION	PHASE	REMARKS
1	ANA	2011.07.14	HND	SYO	APP	






A320 Lightning Strike Experience



Elevator Tip
Composite Skin
Burned.






767 Lightning Data

333 Reports by ATA Chapters

2 years data from 01/01/2005 to 12/31/2006



50% of Lightning Strike Damages of Entire Structure occurs on ATA 53 Fuselage.


Ex: ATA 00, 00000ATA Chapter 00, No of Damage



767 Lightning Data

ATA 53 Damages (172 Reports) by Locations

2 years data from
01/01/2005 to
12/31/2006




74% of Lightning Strike Damage of ATA 53 occurs on Sec. 41 including Radome.

Ex: Radome, 25 Radome damaged, 25 reports



767 Lightning Data

333 Reports by the Dispositions






767 Lightning Data

OTA 53 (172 Reports) by Dispositions


2 years data from
01/01/2005 to
12/31/2006



50% of Lightning Strike Damages of 53 is within Allowable Damage Limit.


Relaxation of ADL could reduce maintenance burden.

Our Proposal for Expansion of ADL of 41 Fuselage Skin.





Proposal: ADL up to 20% Depth for Sec 41 Fuselage Skin.






What ANA did as preventive actions:

Goal: To maintain sufficient conductivity performance

A320

We did:

- Resistance check & correction at the Elevator Trailing Edge Strap to relax maintenance burden.**



The Result was:

Before: 6 Repairs / 1 year

After: Just 1 Allowable damage / 1 year




What ANA did as preventive actions:

Goal: To maintain sufficient conductivity performance

B767

We did:


- Resistance check and correction at the attaching points to relax maintenance burden due to Radome Repair.**





B767

**Lightning Strike - Sec 41 / Radome
Before vs After the correction**



Increase of Radome Composite Repair could be restrained by conductivity correction.

The Result was:
Before: 0.2 Radome Repairs / airplane / year
After: 0.2 Radome Repairs / airplane / year
In Sec 41 Lightning Damage 42% Increased environment,
Radome damage increase was restrained.



Requests to Airplane Manufactures:

- **Establishment of appropriate Conductivity Performance**
- **Establishment of appropriate Allowable Damage Limit**
- **Establishment of appropriate Fly-Back to Main Base criteria.**

