CACRC AE-27 Guidebook: Design of Durable Aircraft Composites: Problems with Sandwich Structure

Eric Chesmar, United Airlines



17 May 2011

# AE-27: Design of Durable, Repairable and Maintainable Aircraft Composites

#### Audience:

• OEM and subcontractor designers to inservice repair issues and problem design details.

#### **Contents:**

 Current design deficiencies of composites as seen in-service.

- Overview of materials and processes
- Examples of poor design detail with examples of preferred alternatives
- Design case studies presenting a discussion on selected problems, successful design case studies.

Available from SAE.org for \$80.



# AE-27: Design of Durable, Repairable and Maintainable Aircraft Composites

- Written by CACRC Design task group, consisting of 9 airlines members and 8 OEMs members
- Content based on survey of over
  15 airlines
- Implementation by outreach to designers at OEMs. Presentations by Design Task Group available upon request.
- Goal to incorporate these lessons learned into company design guidelines
- Success will be measured by not repeating mistakes of the past



# AE-27: Design of Durable, Repairable and Maintainable Aircraft Composites

#### **Airline survey:**

"What are top concerns with composites?"

- Durability & Impact Resistance
- Fluid Ingression
- Erosion
- Overheating
- Protective Finish (Paint)
- Complicated Repairs & Inspection Requirements
  - My interpretation of "complicated" =
    - Non-standardized, different repairs
    - Multiple people and skills required
    - Intermediate approvals or engineering needed



### Impact Resistance:

-FOD

- Ground / Maintenance
  - Service vehicles
  - Service stands
  - Tools
    - Drop
    - Improper use
- Normal line maintenance
  - Opening
  - Latching
  - Over-opening
- Hail



Elevator skin puncture in critical area



#### **Impact Resistance - Hail:**

Design considerations

- Minimum skin gauge
- Minimum honeycomb density
- Skins less than minimum should not be in critical areas, and should have large allowable limits.
  - Repair must be considered during design
- Avoid thin skins in zones that are critical, or have no allowable damage, or not deferrable.

SRM needs to be updated to address:

- Crushed core "soft" but passes tap test
- Remove paint to evaluate damage
- Seal against skin matrix micro-cracking



#### Impact Resistance – Hail:

## Evaluation, Allowable damage and repairability:

- Requires significant time just to evaluate. Consider there may only be cracked or delaminated paint.
- If beyond or not covered SRM, to get approval from OEM, the evaluations must be transferred to maps. Time increases ten-fold.

#### Outboard Elevator after hail



#### Fluid Ingression:

- Hydraulic fluid
  - Fluid leaks are not unusual from many hydraulic system components
  - Difficult if not impossible to remove from damaged parts
  - Protect panels that are below hydraulic components that will leak, such as Belly Fairings and Fan Cowls.



Fan Cowl



#### Fluid Ingression:

- Square-edged panel close-out
  - Porous Foaming adhesive
  - Film adhesive bondline
  - Alum honeycomb edges painted with primer
  - Alum honeycomb corrodes





#### Fluid Ingression:

Close-out of trailing edge wedges – aluminum metalbond

- Ingress through square edge close out and bondline
- Propagation via foaming adhesive
- Failure mode is corrosion of aluminum honeycomb



#### Fluid Ingression:

Close-out of trailing edge wedges

- Square-edged panel close-out without skin covering.
- Phenolic sheet bonded to honeycomb.
- Sealant breaks down over time or sheet is deformed.
- Foaming adhesive allows propagation



X-ray of outboard end of Aileron showing extent of water ingression into honeycomb

Fluid Ingression - Close-out of trailing edge wedges:.

 Original design is a thin sheet bonded with sealant to honeycomb.

 Potting alone on end will crack with age and flexing.



Removed sheet that was covering outboard end.

Alternative – Pot honeycomb Outboard end showing crushed honeycomb.

and wrap skins.



#### Fluid Ingression:

- Through skins
  - Porosity from cure
  - Fracturing of skins and delamination after impact
  - Micro-cracking of matrix



Photomicrograph of impacted skin 3 plies 7781/epoxy prepreg, co-cured in autoclave to honeycomb



#### Fluid Ingression:

Water progression/propagation Through film adhesive

- Over cell walls
- Porosity
- Through cell walls
  - Porous to water vapor



Photomicrograph of film adhesive fillet after autoclave cure



#### Fluid Ingression:

Water progression/propagation (continued)

- Through film adhesive
  - Along scrim/carrier
  - Gaps due to poor fit-up core and skins



Vacuum-bag metalbond repair





E D 颕

#### Fluid Ingression:

- Fasteners through skin into core
- Porous Foaming Adhesive or potting porous so acts as water path
- Honeycomb splices and cavities not completely filled







#### Fluid Ingression – Example of ongoing maintenance issues:

 Water found visually at overnight check. No delamination, no scratches. Tap test fine, but thermography performed showed water scattered across about 30% of surface, but no single area more than 2" on cells with water touching.



## Fluid Ingression – Example of new maintenance issues:

- Checked with OEM for other operator experience.
- Refinished paint
- At engineering direction, deferred repair until next C-check with re-check at A-check.
- Before next check, we bought spare panels with 120 day lead time, built an autoclave tool, and performed 350F prepreg autoclave repair



Inlet Cowl, Outer Barrel, Upper Panel. Close-up of paint

#### **Erosion:**

- Surface mismatch or positive step or facing into wind
- Primarily fairings, leading edge panels, radome
- Can lead to delamination and moisture ingression



Thrust Reverser Sleeve

#### **Overheating:**

- Engine cowls
  - Heat due to normal engine exhaust on pylon panels above and aft of tail cone
  - Actual in-service temperatures and heat higher than design. Example: Accessory compartment hotter due to engine core temperature
  - Heat due to failed valves in openposition
  - Heat from bleed air exhaust



#### **Overheating:**

- Engine cowls
  - Abnormal heat due to failed valves in open-position, or boroscope plug left out
  - Heat from to bleed air exhaust
  - Heat from due to failed valves in open position



#### **Overheating:**

 Air Conditioning exhaust vents on fuselage

- Heat from bleed air exhaust after heat exchanger
- Heat from due to failed valves in open position
- Heat shields used which aren't big enough
- Heat shield materials not



#### Heat shield aft of AC exhaust



#### **Protective Finish (Paint):**

- Needed for protection of structure against UV, moisture, and erosion, etc.
- Observations:
  - Paint is process sensitive many premature failures
  - Fillers and excess thickness still wide-spread practice
- Recommendations
  - Touch up of in-service wear and tear should part be standard maintenance program - monitoring and corrective action program
  - Need to stress cosmetic versus protection functions
  - Need to publish limits to on size and time allowed to defer repainting of bare composite structure for line operations



#### Final thoughts on Fluid Ingression:

- Freeze-thaw cycle commonly identified as failure, but not verified.
- Water lowers adhesive strength
- Honeycomb & Foam Cores both susceptible

#### "Nature abhors a vacuum". Assume water will get in.

- Water can enter as liquid and vapor
- Water continues to accumulate and spread over time until leak path is eliminated or sealed
- Water in honeycomb is inevitable and acceptable
  - Assuming weight not an issue, water does exist inside honeycomb
  - What level is acceptable?
  - For how long will it be acceptable? Propagation rates?



### **Questions?**





.